

Date Completed: \_\_\_\_\_ Failure Code: \_\_\_\_\_

Completed By : \_\_\_\_\_ Signature : \_\_\_\_\_

Accepted By : \_\_\_\_\_ Signature : \_\_\_\_\_

\*\* Delay Codes Legend \*\*

W=Whse    C=CrSp    T=Tag    TL=Tool    P=Plan  
 \*\* Record Time Daily \*\*                      Delays

[illegible]

**\*\* IMPORTANT NOTICE \*\***

YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



IP7011768

## \*\* Work Order Parts List \*\*

Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
1	08074 COUPLING, 00.25 THREADED	S 280225	04/01/04	EA	1	0	1
2	12297 NIPPLE, 00.25 THREADED	S 279343	03/25/04	EA	0	0	0
3	16035 NIPPLE, 00.25 THREADED	S 280579	04/05/04	EA	2	0	2
4	16064 NIPPLE, 00.125 THREADED	S 279364*	03/25/04	EA	7	0	7
5	16065 NIPPLE, 00.125 THREADED	S 280596	04/05/04	EA	1	0	1
6	17987 GAUGE, PRESSURE	S 280225	04/01/04	EA	1	0	1
7	19142 VALVE, NEEDLE	S 279364	03/25/04	EA	2	0	2
8	28635 VALVE, NEEDLE	S 279343*	03/25/04	EA	2	0	2
9	38428 REDUCER, 00.25 BUSHING	S 280225*	04/01/04	EA	3	0	3
10	38429 REDUCER, 00.50 BUSHING	S 279988	03/30/04	EA	2	0	2
11	44361 GAUGE, DIFF PRESSURE	S 280579	04/05/04	EA	1	0	1
12	51610 FITTING, BRASS ELBOW	S 279297*	03/24/04	EA	0	0	0
13	DIRECT THIS IS AN ADDITION TO WORK RELEASE 04-45603-15, FOR ADDITIO	04-45603-7	04/08/04	EA	0	0	0

IP7011769